Durham Research Online

Deposited in DRO:

05 July 2017

Version of attached file:

Accepted Version

Peer-review status of attached file:

Peer-reviewed

Citation for published item:

Donaghy-Spargo, C. M. (2017) 'Rotating electrical machines : Poynting flow.', European journal of physics., 38 (5). 055204.

Further information on publisher's website:

<https://doi.org/10.1088/1361-6404/aa7dcc>

Publisher's copyright statement:

This is an author-created, un-copyedited version of an article published in European Journal of Physics. IOP Publishing Ltd is not responsible for any errors or omissions in this version of the manuscript or any version derived from it. The Version of Record is available online at <https://doi.org/10.1088/1361-6404/aa7dcc> As the Version of Record of this article has been published on a subscription basis, this Accepted Manuscript is available for reuse under a CC BY-NC-ND 3.0 licence after a 12 month embargo period.

Additional information:

Use policy

The full-text may be used and/or reproduced, and given to third parties in any format or medium, without prior permission or charge, for personal research or study, educational, or not-for-profit purposes provided that:

- a full bibliographic reference is made to the original source
- a [link](#) is made to the metadata record in DRO
- the full-text is not changed in any way

The full-text must not be sold in any format or medium without the formal permission of the copyright holders.

Please consult the [full DRO policy](#) for further details.

Rotating Electrical Machines: Poynting Flow

C Donaghy-Spargo¹

Department of Engineering, Durham University, DH1 3LE, UK

E-mail: christopher.spargo@durham.ac.uk

Abstract. This paper presents a complementary approach to the traditional Lorentz and Faraday approaches that are typically adopted in the classroom when teaching the fundamentals of electrical machines - motors and generators. The approach adopted is based upon the Poynting Vector which illustrates the ‘flow’ of electromagnetic energy. It is shown through simple vector analysis that the energy-flux density flow approach can provide insight into the operation of electrical machines and it is also shown that the results are in agreement with conventional Maxwell Stress based theory. The advantage of this approach is its complementary completion of the physical picture regarding the electromechanical energy conversion process - it is also a means of maintaining student interest in this subject and as an unconventional application of the Poynting vector during normal study of electromagnetism.

1. Introduction

A course in elementary rotating electrical machines (motors and generators) is common in physics courses at undergraduate level [1]; this important topic can also be found in pre-university courses and in technical vocational qualifications that contain a reasonable amount of physics content [2,3]. The author has reason to believe that the topic of electrical machines is typically considered ‘less exciting’ than other areas of study. This topic is perhaps most practically important to electrical engineers rather than physicists, however the devices typically studied serve as good illustrators of the underlying physical principles [4,5]. Typically, the traditional methods of teaching how electrical machines fundamentally work are focused around the Lorentz force equation (motors) and Faradays law (generators), ultimately culminating in some ‘equivalent circuit’ model [6]. This paper outlines an alternative approach based on the use of the Poynting Vector in such applications, where it can be seen that calculation of the ‘Poynting flow’, particularly in the air-gap of the machine (the air gap is illustrated in Fig. 1), provides additional insight into the operation of these rotating electrical machines. This method is shown to be complementary to the traditional methods, permitting the development of a more complete physical picture of the energy conversion process and also aiding the maintenance of student

Fig. 1. Industrial induction machine (upper); Induction machine section through A-A', quarter model (lower)

interest in the subject. It is the author's opinion that physical interpretation and understanding of the electromagnetic phenomena exploited in the operation of electrical machinery is of primary importance when teaching the principles of such machines. Of course, mathematics has a role to play, but that mathematics must always aim to enlighten the student with a more complete understanding of the physical picture of the device under study. In this paper, we consider AC rotating electrical machinery, which typically have two modes of operation, motoring and generating.

The Poynting flow approach is presented as a natural step in illustrating the electromechanical energy conversion that takes place at a steady rate when the machine is in steady state operation, its use can also be extended to the complex transients which also take place under fault and transient loading conditions, however, this is beyond the scope of this paper – only the general principles are presented. In the ensuing analysis we consider steady state operating conditions only, machines with linear magnetic circuits, the magnetic cores being considered infinitely permeable ($\mu_r = \infty$), the exciting currents are considered to be perfectly sinusoidal and the spatial distribution of airgap flux density also perfectly sinusoidal. These are standard considerations in electrical machine analysis such that considerable mathematical difficulty

can be overcome. In this paper we consider alternating current electric machinery only, though the Poynting flux method is in general a unified analysis method and can be used for analysing AC and DC rotating machinery, transformers, inductors and other electromagnetic devices.

Firstly a brief review of the 'traditional approaches' to teaching the principles of operation of electrical machines is presented. The concept of the equivalent circuit is then briefly discussed in terms of its usefulness in representing the electromagnetic power flow. The Poynting Vector and the associated Poynting Theorem is then introduced as a refresher – it is shown that the AC electrical machine is an ideal candidate for application of this approach due to its favourable field characteristics. The Poynting theory is then applied to AC electrical machines, specifically to the air-gap electromagnetic fields introduced through simple vector analysis considering a 2D slice of a radial flux machine – the results are then compared with the conventional Maxwell stress point of view and the key results summarised.

2. ‘Traditional’ Approaches

2.1. Motoring Action

The traditional viewpoint [1] when analysing the operation of the motor, is usually the application of the Lorentz force equation relating a current carrying conductor immersed in a magnetic field. A typical example is the force produced on the armature of a DC motor or even an induction motor. The electrodynamic force is used to explain the production of torque in electrical machines and is generally written;

$$\mathbf{T} = \mathbf{F} \times \mathbf{r} = \left(\iiint \mathbf{J} \times \mathbf{B} \, dV \right) \times \mathbf{r} \Rightarrow T = rBIL \quad (1)$$

Here $\mathbf{F}$ is a force on the rotor surface with radius $\mathbf{r}$, the length of the machine is L , the air gap magnetic field is B with an interaction current I flowing in a winding to produce a torque, $\mathbf{T}$. This analysis is sufficient to understand the operation of a motor in terms of measureable effects, i.e. the torque produced on the rotor, however the picture is disjointed when we seek to look for energy (or perhaps power) flow in the device. For example, in an induction motor, the $\mathbf{B}$ field is produced by the stator and a current density $\mathbf{J}$ is developed on the rotor due to that field, then there is a force $\mathbf{J} \times \mathbf{B}$ on those conductors and therefore a torque produced on the motor shaft. It is usual to associate an electrical input power to the stator P_{in} and a shaft mechanical power output P_{out} , knowing both we can compute *energy conversion* efficiency, but this perspective does not give a clear physical picture of how the power ‘transfers’ to the rotor circuits from the stator side circuits and thus how electro-mechanical energy conversion is performed.

2.2. Generating Action

Similarly, when teaching the generator mode of operation of an electrical machine, the traditional approach [1] is usually the application of Faraday’s law (electromagnetic induction), typically presented in the context of the synchronous generator, or perhaps a DC generator of the same configuration as analysed in the motoring mode of operation. The usual mathematical presentation is as below;

$$\int \mathbf{E} \cdot d\mathbf{l} = - \frac{\partial}{\partial t} \iint \mathbf{B} \cdot d\mathbf{S} \Rightarrow e = BLu = \frac{d\phi}{dt} \quad (2)$$

Here, $\mathbf{E}$ is the electric field in a winding, usually considering that the $\mathbf{B}$ field of the synchronous generator is produced by DC coils on the rotor fed by brushes or a brushless exciter. The rotor is then rotated using a prime mover (perhaps a steam turbine) and thus there is a $\frac{\partial}{\partial t}$ present (or there is relative motion of velocity u in one point of view) and as such the stator coils, on the opposite side of the airgap are immersed in this magnetic field, and as such, experience an electric field $\mathbf{E}$ along their axial length due to a changing flux linkage $\frac{d\phi}{dt}$. This is usually presented as in ‘open circuit conditions’; if a load is present, the generator will drive electric current (electrical power) to the connected load. In this mode of operation, it is now convenient to associate a mechanical input power to the rotor P_{in} , and consider an electrical power output P_{out} . Again, this usual analysis does not clearly illustrate the flow of energy, although it is always present in the presentation of these devices that they are *electromechanical energy converters* and energy conversion, in either direction takes place (electrical to mechanical / mechanical

to electrical), depending on the mode of operation (motoring or generating). These principles are perfectly valid, though it is argued that they are incomplete; they deal with conversion, rather than flow, and to fully understand the device, it is important to understand the complete nature of the device.

2.3. A Note on Equivalent Circuits

In practice, a rotating electrical machine fed by alternating current is piece of complex electrical equipment. The aim of any introductory course is not to examine and understand the interactions and behavior of each part of the electrical machine as this is reserved for the specialist machine design engineer, but rather to enable the student to perform calculations on a variety of machines with competency, with a reasonable understanding of the underlying physical principles. Often is the case that an abstraction is made following their learning of the fundamental physical processes (Lorentz & Faraday). Many assumptions are made [4-6] (linear magnetics, sinusoidally distributed currents, infinitely permeable iron sections etc.) in order to simplify any ensuing analysis. This common abstraction is one of transformation from the ‘field’ perspective to ‘equivalent circuit’ perspective – a simpler, but valid approximation of the physical processes which are involved within the machine. In this equivalent circuit abstraction, the magnetic fields present in such machines are typically and conveniently confined to ‘lumped element’ inductances and/or ideal transformer elements and the Joule losses confined to lumped ‘resistive’ elements.

The polyphase induction machine [6] is a classic example of where the *per-phase* equivalent circuit is taught in mainstream undergraduate education and also in widespread use in engineering practice – where an ‘ideal’ transformer is used to represent power flow across the air-gap of an induction machine. There is no doubt that the equivalent circuit representation is a useful one and one of great practical advantage, however, it can be argued that its importance and usefulness in understanding the physical processes and nature of the electromagnetic field distribution that exist within these complex machines is limited. Equivalent circuits themselves give no indication as to the nature and/or consequences of interaction of electric or magnetic fields that enable electrical machines to function as intended – this knowledge must come first. There is no substitute for equivalent circuits, however it is preferable that the student understands the physical processes involved before embarking on the use of equivalent circuits, in order that a fuller understanding of the device that the equivalent is purported to represent is formed.

It is argued by the author that in addition to the fundamental principles such as the Lorentz force and Faradays law, the ‘Poynting flow’ should be considered to complete the physical picture before progressing to equivalent circuit representations.

3. The Poynting Vector & Theorem

In 1884, Oliver Heaviside co-formulated the now named ‘Poynting Vector’ alongside Professor Henry Poynting [7,8]. It is commonly accepted that Poynting vector physically represents the directed energy flux density (i.e. the rate of energy transfer per unit area, or *energy density flow*) of an electromagnetic field. The Poynting Vector, $\mathbf{S}$, in its most common modern form is expressed [9];

$$\mathbf{S} = \mathbf{E} \times \mathbf{H} \quad (3)$$

Where $\mathbf{E}$ and $\mathbf{H}$ are the electric and magnetic field vectors respectively. This vector follows from the Poynting Theorem, an energy-conservation law, where interpretation of the $\mathbf{S}$ vector is to describe the rate of energy flux density from a volume (shown here in integral form);

$$\underbrace{\iiint \mathbf{E} \cdot \mathbf{J} \, dV}_{\text{Real Power}} + \overbrace{\iiint \left[\mathbf{E} \cdot \frac{\partial \mathbf{D}}{\partial t} + \mathbf{H} \cdot \frac{\partial \mathbf{B}}{\partial t} \right] dV}^{\text{Reactive Power}} = - \underbrace{\oint (\mathbf{E} \times \mathbf{H}) \cdot d\mathbf{s}}_{\text{Poynting Flow}} \quad (4)$$

The symbols $\mathbf{E}$, $\mathbf{J}$, $\mathbf{D}$, $\mathbf{H}$ and $\mathbf{B}$ have their usual meaning. The theorem states that the Poynting flow across a closed surface with elemental area $d\mathbf{s}$ is equal to the rate of work done on a given charge distribution (in electrical machines terms, the *real* power) plus the electromagnetic energy density in a region of space (the *reactive* power, in electrical machines terms). Therefore, we can immediately conclude that this appears to be of interest in application to electrical machines due to three distinct reasons;

1. The electrical machine is an electromagnetic (electromechanical) device with varying $\mathbf{E}$ and $\mathbf{H}$ fields present (both temporal and spatial), so we can assume that there is *some* Poynting flow *somewhere*.
2. Electrical machines inherently require energy transfer from one volume to another (e.g. stator to rotor) – separated by an *airgap* where energy conversion appears to take place, either from electrical to mechanical (motor) or from mechanical to electrical (generator).
3. Focus is not usually placed in the airgap, but rather the conductors either side of the airgap – we desire to understand the process in between these two regions

It is clear that the region of immediate interest is the boundary layer of air between the rotary and stationary components of rotary machines (this may also be considered in linear electrical machinery). As students will usually (and should) have covered some elementary electromagnetic theory before tackling electrical machines, an approach to examine the Poynting flow is not unreasonable. Such analysis should be intended as an effort to aid understanding and the presentation of an alternative and complementary viewpoint when venturing into the topic of rotary electrical machines. The viewpoint has been investigated somewhat in the realms of specialist electrical engineering research [10-14], but is by no means a mainstream method of analysis and is practically unknown within the teaching of electrical machinery, even to seasoned academics.

The Poynting vector is now used in the air-gap analysis of an alternating current rotary electrical machine. Use is made of simple vector analysis and the concept of the ‘rotating magnetic field’, both of which should be familiar to undergraduate students in physics and engineering.

4. AC Electrical Machinery

Consider a polyphase rotary electrical machine [6] as an electromechanical energy converter, such as the induction motor or synchronous generator. In these machines, a cylindrical rotor rotates in a cylindrical stator, separated by a small air-gap – a mechanical clearance. If we consider motoring operation, alternating current electrical power is fed into the stator of the machine and an appropriate system of conductors and magnetic core is designed to set up a rotating magnetic field in the air-gap, rotating at an angular velocity (the synchronous speed) about the axis of the machine which is

determined by the pole P number and the supply frequency f_s . Considering the Poynting vector $\mathbf{S}$, it will be shown that the airgap provides a space in which electrical energy can flow into and across an iron-air boundary and flow unimpeded to another air-iron boundary in order to facilitate electromechanical energy conversion.

5. Airgap Poynting Flow

In analysing the Poynting vector in AC machines, the $\mathbf{E}$ and $\mathbf{H}$ fields present must be described – focus is placed on the air-gap region. Considering only a 2-dimensional ‘slice’ or ‘cross section’ of a radial flux machine (such as the induction machine or the synchronous generator), the air-gap magnetic field vector $\mathbf{H}_{\text{gap}}$ can be described vectorially in a cylindrical co-ordinate system at each point in the air gap as;

$$\mathbf{H}_{\text{gap}} = H_r \hat{\mathbf{r}} + H_\theta \hat{\boldsymbol{\theta}} \quad (5)$$

Where $H_r \hat{\mathbf{r}}$ is a radially directed component and $H_\theta \hat{\boldsymbol{\theta}}$ is a circumferentially directed component. Note that there is no axial component in $\hat{\mathbf{z}}$. The ‘magnetic flux lines’, often used to visualise the field in electromagnetic devices are contours of constant magnetic vector potential $\mathbf{A}$, this is an auxiliary vector quantity often used for computation in electrical machines. Figure 2 shows the magnetic vector potential plot of a four-pole induction motor, computed using a 2D non-linear finite element model.

Fig. 2. Magnetic vector potential distribution

Fig. 3. Magnetic flux density distribution

The magnetic vector potential is linked to the air-gap magnetic field through the following equation;

$$\nabla \times \mathbf{A}_{\text{gap}} = \mu_0 \mathbf{H}_{\text{gap}} = \mu_0 (H_r \hat{\mathbf{r}} + H_\theta \hat{\boldsymbol{\theta}}) \quad (6)$$

It should be noted that in the machine air gap, the permeability $\mu_0 \mu$ used in the constitutive relation $\mathbf{B} = \mu_0 \mu \mathbf{H}$ is for all purposes equal to vacuum permeability and therefore represents a linear isotropic relation, permitting the use of the principle of superposition. Therefore, it follows from Faraday that there exists an induced electric field in the airgap;

$$\nabla \times \mathbf{E}_{\text{gap}} = -\frac{\partial}{\partial t} \nabla \times \mathbf{A}_{\text{gap}} \quad (7)$$

$$\Rightarrow \mathbf{E}_{\text{gap}} = -\frac{\partial \mathbf{A}_{\text{gap}}}{\partial t} = -\frac{\partial}{\partial t} (H_r \hat{\mathbf{r}} + H_\theta \hat{\boldsymbol{\theta}}) = -\frac{\partial A_z}{\partial t} \hat{\mathbf{z}} \quad (8)$$

Due to the involvement of $\nabla \times$, the induced airgap electric field $\mathbf{E}_{\text{gap}}$ is axial in direction $\hat{\mathbf{z}}$, and it should also be noted that $\mathbf{E}_{\text{gap}} = \mathbf{E}_{\text{gap}}(r, \theta, t)$ as the magnetic vector potential A_z is typically a spatial and temporal sinusoidal function;

$$A_z(\theta, t) = \widehat{A}_z \cos(p\theta - 2\pi f_s t) \quad (9)$$

The magnetic vector potential in the air-gap is a travelling wave and its frequency depends on the number of pole pairs p of the machine and the speed at which it travels on the injected electrical frequency f_s . Figure 3 shows the typical characteristic of the axial component of the magnetic vector potential $A_z(\theta, t)$ in the air-gap of an AC machine. This is the well known ‘rotating magnetic field’ first described by Nikola Tesla and perhaps most eloquently demonstrated by Tesla’s *Egg of Columbus*. Therefore, it naturally follows from the Poynting theorem that there must be, in a region with $\mathbf{H}_{\text{gap}}$ and $\mathbf{E}_{\text{gap}}$ in co-existence, an air-gap Poynting flux;

$$\mathbf{S}_{\text{gap}} = \mathbf{E}_{\text{gap}} \times \mathbf{H}_{\text{gap}} \quad (10)$$

This axial electric field caused by this time varying magnetic vector potential is thus used in conjunction with the originating air gap magnetic field intensity to form a Poynting Vector - an energy flux density flow in the airgap of the machine. This flux, in general terms, represents the electromagnetic power reaching the airgap from the stator and therefore the electromagnetic energy transferred in accordance with the Poynting theorem – the flow of energy flux density across the rotor enclosing surface. Included in this transfer is the proportion dissipated as rotor losses (both DC & AC winding and iron losses) and the proportion being converted to mechanical power at the shaft output, in the motoring case. Two key cases can now be presented to illuminate the fact that there is a Poynting flux in the airgap. The first is the case of the ‘unloaded’ machine (no mechanical torque applied to the rotor of a motor or an electrical load connected to a generator), where if the airgap is considered smooth and the rotor is a simple high permeable cylinder with no conducting regions or exhibit any saliency, the airgap magnetic field is known to be purely radial when crossing the airgap and thus the Poynting flux can be found, in the steady state, to be purely circumferential in nature as a consequence;

$$\mathbf{S}_{\text{gap}} = S_{\text{gap}} \hat{\boldsymbol{\theta}} = -\frac{\partial A_z}{\partial t} \hat{\mathbf{z}} \times H_r \hat{\mathbf{r}} = E_z \hat{\mathbf{z}} \times H_r \hat{\mathbf{r}} \quad (11)$$

This is a surprising result as it suggests that the energy flux density is circulating within the airgap. However, the true value of this analysis is only visible when we investigate a practical machine design, such as the induction motor with its embedded rotor conductors short circuited by end-rings in a *squirrel cage* design or in the case of a *synchronous reluctance motor* with high rotor saliency. The scene in the airgap of an unloaded machine is presented in Figure 4.

Fig. 4. Air-gap vectors – unloaded AC machine

In practical machine designs, any energised rotor conductors induce an additional airgap magnetic field, and in the case of the reluctance motor, the saliency modifies the airgap permeance function away from assumed uniformity – both effects result in perturbing the airgap magnetic field from its purely radial nature when the machine is under load and introduce a circumferential airgap magnetic field component $H_\theta \hat{\theta}$. For example at the airgap-iron boundary in an induction machine, the conductors consisting of a number of turns (or perhaps solid bars in a caged rotor machine) are placed in slots (Fig. 1). When a current flows, this source of magneto-motive force contributes to a tangential magnetic field component H_θ which can be found via the application of Amperes circuital law around the conductor periphery² [15]. The introduction of this component in turn alters the Poynting vector as follows;

$$\mathbf{S}_{\text{gap}} = S_r \hat{\mathbf{r}} + S_\theta \hat{\theta} = E_z \hat{\mathbf{z}} \times (H_r \hat{\mathbf{r}} + H_\theta \hat{\theta}) \quad (12)$$

The components of the Poynting flow can be calculated;

$$\begin{aligned} S_r \hat{\mathbf{r}} &= E_z \hat{\mathbf{z}} \times H_\theta \hat{\theta} \\ S_\theta \hat{\theta} &= E_z \hat{\mathbf{z}} \times H_r \hat{\mathbf{r}} \end{aligned} \quad (13)$$

It is straightforward to see that the axial component of Poynting Vector, $S_z \hat{\mathbf{z}}$ is identically zero. The radial component is of most interest as it is this component that transfers energy across the airgap – the axial electric field $E_z = \frac{\partial A_z}{\partial t}$ and the tangential magnetic field in the airgap $H_\theta \hat{\theta}$ are therefore the key components. The ‘loaded’ machine scenario is presented in Figure 5.

² $\oint \mathbf{H} \cdot d\mathbf{l} = H_\theta \Delta x$ where Δx is the slot opening width, assuming that the magnetic core has $\mu \rightarrow \infty$. Note that H_θ changes sign with a change in current direction. For a detailed explanation, the reader is advised to consult [15].

Fig. 5. Air-gap vectors – loaded AC machine (motoring)

Therefore, in the case of a motor, the Poynting vector is no longer purely circumferential and circulatory in nature, but now, is directed at some angle determined by the loading level of the machine, into the rotor, transferring the power loss and the mechanical output power as radiated electromagnetic energy flux density over the rotor surface. This perspective is an additional viewpoint that is useful in teaching students how AC electrical machinery operates, clearly and explicitly showing the electromagnetic energy transfer across the airgap between the stator and rotor and the necessary conditions required (field components). It is noted that electrical machines appear to be useful only when a circumferential component of airgap magnetic field exists to create a component of Poynting vector radially inward to the rotor for a motor, or, if we seek to understand generator operation, the vector direction is reversed such that the Poynting vector is radially outward from the rotor surface into the stator, reversing the energy flow. A brief summary of key results for AC rotating machines is provided in Table I for reference.

	E_z direction	$H_r \hat{r}$	$H_\theta \hat{\theta}$	$S_r \hat{r}$	$S_\theta \hat{\theta}$	S_{gap} direction (w.r.t rotor)
Unloaded	$\pm \hat{z}$	non-zero	zero	zero	non-zero	circumferential
Loaded motor	$+\hat{z}$	non-zero	non-zero	non-zero	non-zero	tending radially inward
Loaded generator	$-\hat{z}$	non-zero	non-zero	non-zero	non-zero	tending radially outward

Table I – Key Results: Airgap Poynting Flow

Therefore, the elementary analysis of AC machines using the Poynting Vector and the Poynting theorem suggests that in order for an AC machine to facilitate electromechanical energy conversion and for a given machine to maximise the rate of energy conversion, it is the radial component of interest, radiating either inwardly or outwardly from the rotor - depending upon the mode of operation.

The airgap is the medium in which the energy flux density radiates before impinging on the bounding surface of either the rotor (motor) or stator (generator). Correct integration of the Poynting vector describes the electrical power transferred across the airgap available for conversion – this is best

performed with thorough mathematical analysis in complex form and it is beyond the scope of aim of this paper to present such a detailed mathematical analysis of the flow in the airgap. However, to show that the results are consistent with traditional theory, we can consider the Maxwell Stress Tensor [9]. It is common that the Maxwell Stress description of the rotor surface tractive effort is traditionally employed in more advanced electrical machine analysis, and for implementation in finite element models. It can be shown that the rotor surface tangential force density (torque producing component) is written [4-6];

$$\left(\iint \mathbb{M} \cdot d\mathbf{S} \right)_{\theta} = F_{\theta} = B_r H_{\theta} A = \mu_0 H_r H_{\theta} A \quad (14)$$

Here, $\mathbb{M}$ is the Maxwell stress tensor distributed over the rotor surface. It is clearly seen that there is no tractive effort upon the rotor surface if the conditions in the airgap are such that $H_{\theta} = 0$ and hence from the Poynting viewpoint $S_r = 0$. This result therefore fully agrees with previous result that H_{θ} is required in order to facilitate useful energy transfer across the airgap in rotating AC machines. Without this tangential component, the machine would simply not work as intended. It must be noted that if a more general analysis is performed, radial, tangential and axial components of both the $\mathbf{E}$ and $\mathbf{H}$ fields will exist. Some of these flows will be of interest, however it is the radial flow that is key to electromagnetic energy transfer across the air gap.

6. Conclusions

This paper has illustrated by the way of simple vector analysis that the Poynting Vector approach to electromagnetic energy transfer in common alternating current machines can provide useful insight into the processes that govern machine operation. It is shown that an airgap electric field is induced due to the time varying magnetic vector potential in that airgap, this axial electric field then interacts with the radially directed air-gap magnetic field to produce a circulating electromagnetic energy flow in the air-gap of an unloaded (non-torque producing, lossless) electrical machine, a Poynting vector exists. When the resultant air-gap magnetic field is perturbed by a tangential magnetic field under machine mechanical loading, a radial component of the Poynting vector develops to facilitate electromagnetic energy transfer across that air-gap. The existence of a directed electromagnetic energy flow in the air-gap of an electrical machine complements the traditional approaches typically adopted in the classroom and the key results obtain through the Poynting flow analysis can be shown to agree with the Maxwell Stress Tensor approach. This method of attack can provide a complementary physical picture and provide an unusual exemplar application of the Poynting vector in physics and engineering courses at undergraduate and graduate levels.

7. References

- [1] H. D. Young, et al, University Physics with Modern Physics, 12th Edition, Pearson, 2007
- [2] AS & A-Level Physics Specification, Version 1.2, AQA, December 2015
- [3] BTEC Level 3 Diploma in Electrical/Electronic Engineering Specification, Issue 2, June 2016
- [4] P. Hammond, Applied Electromagnetism, Pergamon Press, 1971
- [5] J. Turowski, Engineering Electrodynamics, CRC Press, 2014
- [6] D. Gerling, Electrical Machines: Mathematical Fundamentals of Topologies, Springer, 2015
- [7] O. Heaviside, "Electromagnetic Induction and its Propagation", *The Electrician*, 1885
- [8] J. H. Poynting, "On the transfer of energy in the electromagnetic field." *Philosophical Transactions of the Royal Society of London* 175 (1884): 343-361

- [9] J. Jackson, Classical Electrodynamics, 3rd Revised Edition, John Wiley & Sons, 1998
- [10] J Slepian, "Energy Flow in Electrical Systems - The Energy-Flow Postulate", AIEE Transactions (Electrical Engineering), vol. 61, Dec. 1942, pp. 835-41.
- [11] E. I. Hawthorne, "Flow of energy in synchronous machines," in *Transactions of the American Institute of Electrical Engineers, Part I: Communication and Electronics*, vol. 73, no. 1, pp. 1-10, March 1954
- [12] J. A. Ferreira, "Application of the Poynting vector for power conditioning and conversion," in *IEEE Transactions on Education*, vol. 31, no. 4, pp. 257-264, Nov. 1988
- [13] L. S. Czarnecki, "Could power properties of three-phase systems be described in terms of the Poynting vector?," in *IEEE Transactions on Power Delivery*, vol. 21, no. 1, pp. 339-344, Jan. 2006
- [14] Z. Cekareski, A. E. Emanuel, "Poynting vector and the power quality of electric energy", *Eur. Trans. Elect. Power*, vol. 11, no. 6, pp. 375-382, 2001
- [15] M. G. Say, "Alternating Current Machines", Pitman Publishing, 1976